

SH-600HD Repair Instructions

SOFTWARE NOTICE

All software is offered "as is" and without guarantee. This software is for experienced users only. If you don't have the ability to load this software or if you feel unsure of your abilities, DO NOT use this software. Sathero Meters is in no way responsible for the use or mis-use of this software. Any repairs required because of your use or mis-use of this software will be charged at normal bench repair rates and normal replacement parts cost. By using this software you are agreeing to these terms.

USE THIS SOFTWARE AT YOUR OWN RISK

If your SH-600HD fail during a upgrade, use the included file to repair your SH-600HD.

Caution: Follow the directions carefully to insure proper repair of your SH-600HD

1. Copy the included repair software (SH600HD.ssu) as attached into USB root directory
Reminder: do not change file name
2. Insert USB into SH-600HD USB interface
3. Turn on your SH-600HD
4. After 5mins, restart your SH-600HD

Website: <http://SatheroMeters.com>

Email: sales@SatheroMeters.com