

SH-400HD Repair Instructions

1. Copy the repair software to the USB drive root directory
Important: do not change file name
2. Insert USB drive into SH-400HD USB interface
3. Press and hold the F1 button, turn on the meter
4. Release F1 button when the LED light flashes
5. Wait for the meter auto restart

All software is offered "as is" and without guarantee. This software is for experienced users only. If you don't have the ability to load this software or if you feel unsure of your abilities, DO NOT use this software. DMS International is in no way responsible for the use or mis-use of this software. Any repairs required because of your use or mis-use of this software will be charged at normal bench repair rates and normal replacement parts cost. By using this software you are agreeing to these terms.

USE THIS SOFTWARE AT YOUR OWN RISK

These files may NOT be freely distributed and may NOT modified in any way. This comment must remained attached to the files.

All materials contained in this document are protected by United States and international copyright law and may not be reproduced, distributed, transmitted, displayed, published or broadcast without the prior written permission from Tim Heinrichs. You may not alter or remove any file, document, trademark, copyright or other notice from copies of the content.